## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	347	(brace and (drive or motor or spindle or "triple spindle")).clm.	US-PGPUB	OR	OFF	2007/11/20 12:08
L5	4	("continuous passive motion" and (limb or arm or shoulder) and control and position\$3).clm.	US-PGPUB	OR	OFF	2007/11/20 12:10
L6 .	1	("continuous passive motion" and unit and electromotor).clm.	US-PGPUB	OR	OFF	2007/11/20 12:11
L7	3	("continuous passive motion" and unit and motor).clm.	US-PGPUB	OR	OFF	2007/11/20 12:11
L8	9	(limb and joint and drive and unit and motor).clm.	US-PGPUB	OR	OFF	2007/11/20 12:12
L9	· 14	("continuous passive motion").clm.	US-PGPUB	OR	OFF	2007/11/20 12:12